

Work Order ID 62136

September 16, 2010 1:45:35 PM



Page 1

Item ID: D4009-5

Accept



Setup Start



Revision ID:

Stop



Item Name: Ground Strap

Start Date: 9/16/10 Start Qty: 6.00



Cust Item ID:

Required Date: 9/30/10 Req'd Qty: 6.00



Customer:

Reference:

Approvals: Process Plan: C2 Date: 10/9/16 Tooling:

Date:

Run Start



QC: Date: SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D4009

A

100

0.00



Small Fab

Memo

0.00

Small Fab

I- Cut to size as per dwg D4009

SB 10/11/03 (6)

110

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

SB 10/11/03

(6)

120

Identify as per dwg & Stock Location 112

0.00



Packaging

Memo

0.00

Packaging

11/1/14 (6)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 62136

September 16, 2010 1:45:35 PM



Page 2

Item ID: D4009-5

Accept



Setup Start



Revision ID:

Stop



Item Name: Ground Strap

Start Date: 9/16/10 Start Qty: 6.00



Cust Item ID:

Required Date: 9/30/10 Req'd Qty: 6.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/11/05 *[Signature]*
MF
10-11-4

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

September 16, 2010 1:45:34 PM

Page 1

Work Order ID: 62136



Parent Item: D4009-5



Parent Item Name: Ground Strap

Start Date: 9/16/10

Required Date: 9/30/10

Start Qty: 6.00

Required Qty: 6.00

Comments: IPP rev A 09.12.23 new Issue Prelim EC verified by: DD IPP Rev:B
10.05.03 as per ECN10-562 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D4009		Manufactured	No			100	Each	43.7500	1.125	6.75			
-------	--	--------------	----	--	--	-----	------	---------	-------	------	--	--	--



Ground Strap



Location

Loc Qty

Loc Code

ST

43.75

57049

43.75

9/30/10/03

6.75

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART AEROSPACE PART NUMBER	JOHN CAMERON AVIATION PART NUMBER
D4009-3	REF JCA-M47-4-01
D4009-5	REF JCA-M47-4-01

SPECIFICATION CONTROL DRAWING



DART PART NUMBER	LENGTH "L"
D4009-3	1.5
D4009-5	13.5

D4009-X GROUND STRAP

C21019114
W10:62136

RELEASED
2010-05-05
MS

NOTES:

- 1) MATERIAL: MADE FROM AVIALL P/N 1171 (OR SEA-171) OR C.O.R.E. AVIATION P/N QQ8575R36T250
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: N/A
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: N/A

DESIGN		DART AEROSPACE LTD	
DRAWN	<i>MS</i>	HAWKESBURY, ONTARIO, CANADA	
CHECKED	<i>MS</i>	DRAWING NO.	REV. A
MFG. APPR.	<i>MS</i>	D4009	SHEET 3 OF 5
APPROVED	<i>MS</i>	TITLE	SCALE
DE APPR.	<i>MS</i>	GROUND STRAP	NTS
DATE	10.02.05	<small>COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD</small>	

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries